

Willow St Crawlspace & Subslab Study

#	Address	Rationale for Inclusion in Phase II Investigation	Crawlspace Sample	Exterior Upwind Background Sample	Subslab Sample
1	2852 Willow St	Next Door to 2848 Willow St where the soil-gas concentration exceeded USEPA and NCDENR acceptable risk levels.		1	1
2	2848 Willow St	Soil-gas concentration exceeded USEPA and NCDENR acceptable risk levels.		1	1
3	2835 Willow St Apt 1	Soil-gas concentration exceeded USEPA and NCDENR acceptable risk levels.		1	1
4	2835 Willow St Apt 2	Soil-gas concentration exceeded USEPA and NCDENR acceptable risk levels.		1	1
5	2831 Willow St Apt 1	Soil-gas concentration nearly exceeded USEPA and NCDENR acceptable risk levels.		1	1
6	2831 Willow St Apt 2	Soil-gas concentration nearly exceeded USEPA and NCDENR acceptable risk levels.		1	1
7	2828 Willow St	Soil-gas concentrations nearly exceeded USEPA and NCDENR acceptable risk levels.		1	1
8	2310 Old Steele Creek Rd	We were unable to collect soil-gas samples from here on two attempts and it is next to a well with an elevated PCE concentration.			1
			TOTALS	6	2

Note: The number of Exterior Upwind Background Samples shown above is conservative. Given how close together the Crawlspace Samples are, we may be able to simply collect one Exterior Upwind Background Sample per day when Crawlspace Samples are collected.